


## INTELLICHLOR®



## INTELLICHLOR®

### Replacement Parts

No.	Part No.	Description	Part No. Includes
1	H-52-0595	Replacement Union Set	2
2	520735	Flow Switch replacement kit	1
Not Shown			
	H-52-0881	Replacement Cell IC20	
	H-52-0882	Replacement Cell IC40	
	H-52-0883	IC20 & IC40 Transfo	
	H-52-0884	Spacer Cell (for start-up or winterization)	
		Acid Washing Kit	
	520670	(incl. Closed end union cap, o-ring and coupling nut)	
	521147	Gasket Kit - Set of 10 o-rings	
	H-52-0594	Diagnostic Wand	